
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/B737/121 Amdt 2.

Boeing 737 Series Aeroplanes

**AD/B737/121
Amdt 2**


Fuel Boost Pump Wiring

3/2008

Requirement: CANCELLED.

This AD is cancelled on 13 March 2008.

Background: This Directive has been superseded by AD/B737/303 Amendment 1.



Charles Lenarcic
Delegate of the Civil Aviation Safety Authority

23 January 2008