
AIRWORTHINESS DIRECTIVE

For the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/B737/179.

Boeing 737 Series Aeroplanes

AD/B737/179

Fuel Hose Quick Disconnect Coupling

3/2003

Requirement: CANCELLED.

Background: This Directive, based on FAA AD 99-03-08, is superseded by AD/B737/207 which is based on FAA AD 2002-14-21.



James Coyne
Delegate of the Civil Aviation Safety Authority

30 January 2003