

Boeing 747 Series Aeroplanes

---

**AD/B747/27**                      **Escape Slide Flapper Valve - Modification**                      **2/81**

Applicability: All models 747 with B.F. Goodrich escape slides and turbo fans identified in B.F. Goodrich SB No. 25-060 dated 14 July 1980.

Documents: 1. FAA AD 80-20-02, Amendment 39-3928; or  
2. Boeing SB 747-25-2543; OR 3. B.F. Goodrich SB 25-060.

Compliance: Before 1 January 1981.

Background: Some escape slides on overseas aeroplanes have failed to inflate correctly during emergency test inflation.