

Boeing 747 Series Aeroplanes

AD/B747/182

Internal Skin Doublers at BS 460

10/98

Requirement: CANCELLED.

Background: The requirements of this directive are contained in AD/B747/160.