

Boeing 767 Series Aeroplanes

---

**AD/B767/83**

**Flight Station Window Latch**

**11/95**

Applicability: Model 767 series with line numbers 1 through 114.

Requirement: Modify the latch hook installation for the number two flight station window frame in accordance with Boeing Service Bulletin 767-56-0002.

*Note: FAA AD 94-18-01 Amdt 39-9014 refers.*

Compliance: Before 11 April 1997.

Background: The FAA received reports of the flight crew executing rejected takeoffs and air turnbacks due to false “closed” indications for the number two flight station window.