

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/BEECH 1900/3.

---

### Beechcraft 1900 Series Aeroplanes

**AD/BEECH 1900/3**

**Wing Fasteners**

**11/2009**

Requirement: CANCELLED.

This AD is cancelled on 22 October 2009.

Background: This AD, raised in 1990 against Beechcraft Mandatory Service Bulletin (SB) No. 2336, required an inspection to ensure proper installation information pertaining to fasteners at the wing skin/keel rib area. Fasteners may have been required in the affected area to meet design requirements. Compliance was required at the next scheduled inspection for issue of Maintenance Release after 22 March 1990.

As all affected aircraft would have been inspected, and, if necessary, modified long ago, this AD is no longer required.



David Villiers  
Delegate of the Civil Aviation Safety Authority

4 September 2009