

Casa 212 Series Aeroplanes

---

**AD/CASA/2**

**Engine Firewall Sealing**

**12/82**

Applicability: Model 212 with S/Nos. as detailed in Casa SB No. 212-73-03, Rev. 1.

Document: Casa SB No. 212-73-03, Rev. 1.

Compliance: If not already accomplished within 100 hours time in service after 31 December 1982.

Background: Manufacturer's requirement to improve fireproofing at the engine firewall.