
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AS 355/15 Amdt 1.

Eurocopter AS 355 (Twin Ecureuil) Series Helicopters

**AD/AS 355/15
Amdt 1**

**Sliding Door Ball Joint - Inspection
and Modification**

8/2009

Requirement: CANCELLED.

This AD is cancelled on 30 July 2009.

Background: This unique Australian AD specified inspection in accordance with Aerospatiale Telex Service 05.11 and SB No. 52-01 at intervals not exceeding 300 hours time in service until modified. The AD is no longer required.



David Villiers
Delegate of the Civil Aviation Safety Authority

18 June 2009