

Eurocopter AS 355 (Twin Ecureuil) Series Helicopters

AD/AS 355/21 Starflex Arms and MGB Suspension Bars 10/86

CANCELLED - Superseded by AD/AS 355/22.

Background: The manufacturer after further investigation, believes the problem is associated with a vibration frequency, coupled with lack of stiffness of certain components. A more extensive inspection procedure has been called for which varies from the original Directive.