
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AS 355/31.

Eurocopter AS 355 (Twin Ecureuil) Series Helicopters

AD/AS 355/31

Tail Rotor Gearbox Casing

8/2009

Requirement: CANCELLED.

This AD is cancelled on 30 July 2009.

Background: This unique Australian AD specified modification and periodic inspection of tail rotor gearbox casings in accordance with SB No. 05-18. After modification, inspection was required at intervals not exceeding 400 hours time in service. CASA's SDR database does not contain a relevant report. Use of an AD to mandate this 400 hourly inspection is no longer justified.



David Villiers
Delegate of the Civil Aviation Safety Authority

18 June 2009