
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AS 355/32.

Eurocopter AS 355 (Twin Ecureuil) Series Helicopters

AD/AS 355/32

Servo Control Securing Screws

8/2009

Requirement: CANCELLED.

This AD is cancelled on 30 July 2009.

Background: This unique Australian AD specified inspection and torque checking of screws within 25 hours CTIS after May 1988. The AD was not based on a manufacturer's service document. The AD is no longer required.



David Villiers
Delegate of the Civil Aviation Safety Authority

18 June 2009