
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/B-2/7.

Brantly B-2 Series Helicopters

AD/B-2/7 **Main Rotor Blade Dampers - Installation** **6/2009**

Requirement: CANCELLED.

This AD is cancelled on 4 June 2009.

Background: This AD, issued in 1960, required the installation of a revised main rotor damping system in accordance with Brantly SL No. 2 to reduce the blade swinging. The AD compliance was forthwith. As all aircraft would have been modified, the AD is no longer required.



James Coyne
Delegate of the Civil Aviation Safety Authority

24 April 2009