
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AA-5/4.

Gulfstream (Grumman American/ American Aviation) AA-5 Series Aeroplanes

AD/AA-5/4

Aileron - Additional Drain Holes

6/2009

Requirement: CANCELLED.

This AD is cancelled on 4 June 2009.

Background: This AD, issued in 1972, required modification of the ailerons in accordance with American Aviation SB No. 132 by incorporating additional drain holes. The AD compliance was within 100 hours time in service after 30 November 1972. As all aircraft would have been modified, the AD is no longer required.



James Coyne
Delegate of the Civil Aviation Safety Authority

24 April 2009