

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AA-5/25.

---

### **Gulfstream (Grumman American/ American Aviation) AA-5 Series Aeroplanes**

**AD/AA-5/25**

**Elevator Drain Holes - Inspection  
and Modification**

**6/2009**

Requirement: CANCELLED.

This AD is cancelled on 4 June 2009.

Background: This AD, issued in 1980, required inspection and, if necessary, modification of the elevator drain holes in accordance with Grumman American SB No. 169 to ensure water was not collecting in the trailing edge of the elevators. The AD compliance was within 100 hours time in service after 30 June 1980. As all aircraft would have been inspected by now, the AD is no longer required.



David Villiers  
Delegate of the Civil Aviation Safety Authority

24 April 2009