
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AC-SNOW/4.

Ayres Thrush (Snow) Commander Series Aeroplanes

AD/AC-SNOW/4 Deflector Cable Assembly - Modification 9/2008

Requirement: CANCELLED.

This AD is cancelled on 28 August 2008.

Background: This AD, raised in 1968 against Aero Commander - Olney Division Service Letter (SL) No. 43, required a modification to relocate the deflector cable turnbuckle to prevent failures as a result of vibration. Compliance was required forthwith. As all affected aircraft would have been modified by now, this AD is no longer required.



David Villiers
Delegate of the Civil Aviation Safety Authority

18 July 2008