

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AC/27.

---

### **Twin Commander (Gulfstream/Rockwell/Aerocommander 500, 600 and 700) Series Aeroplanes**

**AD/AC/27**

**Main Landing Gear Actuating  
Cylinder Body - Inspection**

**8/2008**

Requirement: CANCELLED.

This AD is cancelled on 31 July 2008.

Background: This unique Australian AD, issued prior to 1962 against Aero Commander Service Letter (SL) No. 130, required an inspection for cracks of the main landing gear actuating cylinder bodies.

Compliance was forthwith.

As all affected aircraft would have been inspected by now, this AD is considered to be no longer required.



James Coyne  
Delegate of the Civil Aviation Safety Authority

13 June 2008