

Twin Commander (Gulfstream/Rockwell/ Aerocommander 500, 600 and 700) Series Aeroplanes

AD/AC/50 Unfeathering Pump Supply Line - Replacement 8/73

Applicability: Model 690 with S/Nos. 11001 to 11063.

Document: 1. Aero Commander SB No. 123A; or
 2. FAA AD 73-13-9.

Compliance: Within 100 hours time in service after 31 August 1973.