AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AC/57.

Twin Commander (Gulfstream/Rockwell/Aerocommander 500, 600 and 700) Series Aeroplanes

AD/AC/57 Pre-Certification Requirements - Modifications 8/2008

Requirement: CANCELLED.

This AD is cancelled on 31 July 2008.

Background: This unique Australian AD, issued in 1975, required installation of fuelling

equipment bonding points at each fuel filling point, and identification of external earthing points for attachment of ground connections on each main undercarriage

assembly, or nose gear.

Compliance was before 31 March 1975.

As these requirements were in accordance with cancelled ANO 101.22, the

requirements of this directive are no longer appropriate.

James Coyne

Delegate of the Civil Aviation Safety Authority

18 June 2008