
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AC/60.

Twin Commander (Gulfstream/Rockwell/Aerocommander 500, 600 and 700) Series Aeroplanes

AD/AC/60 Aft Facing Seats - Placard - Installations 8/2008

Requirement: CANCELLED.

This AD is cancelled on 31 July 2008.

Background: This unique Australian AD, raised in 1975 against Rockwell International (also known as Aero Commander) Service Bulletin (SB) No. 155, required installation of seat and shoulder harness placards of rear facing passenger seats to comply with applicable US Federal Aviation Regulation (FAR). Compliance was before further flight with any passenger seat installed in the aft facing position. As all affected aircraft would have been modified by now, this AD is no longer required.



David Villiers
Delegate of the Civil Aviation Safety Authority

20 June 2008