

Twin Commander (Gulfstream/Rockwell/ Aerocommander 500, 600 and 700) Series Aeroplanes

**AD/AC/63                      Electric Elevator Trim Speed - Modification                      4/77**

Applicability:    Model 690A S/Nos. 11143 thru 11344 equipped with a Rockwell international installed Collins Radio Company AP 106 auto pilot (this AD does not apply to installations made in accordance with STC SA 1876 SW).

Document:        1.    Rockwell International SB No. 162, Rev. 1 or  
                         2.    FAA AD 77-04-01.

Compliance:    Part I - Before 30 April 1977.  
  
                         Part II - Must be accomplished prior to re-activation of manual electric trim.