

Aermacchi - Lockheed AL 60 Series Aeroplanes

AD/AL 60/4 Engine - Exhaust Manifold Failures - Inspection 6/63
Amdt 1

Applicability: All models equipped with Continental TSIO-470-B engine.

Document: Aermacchi Lockheed 60 SB No. 1.

Compliance: At intervals not exceeding 100 hours time in service after 1 September 1971.