

Auster/Beagle A.61 Series Aeroplanes

---

**AD/AUS/6  
Amdt 1**

**Tailplane Bracing**

**5/95**

Applicability: All models manufactured before January 1947.

Requirement: Visually inspect the tailplane bracing wire strap fittings for cracks near the retaining bolts.

*Note: The pilot in command may perform, endorse and certify on the Maintenance release for this inspection.*

Compliance: Before the first flight of the day.

This AD is effective from 27 April 1995.

Background: Cracks have been detected in the bracing wire attachment fittings.

This amendment allows the pilot in command to perform the inspection.