

Cessna 170, 172, F172, FR172 and 175 Series Aeroplanes

---

**AD/CESSNA 170/52**

**Muffler**

**3/86**

Applicability: Cessna aircraft S/N 172RG 1135 to 172RG 1187.

Requirement: Inspect muffler core below each end plate attachment screw for damage in accordance with Cessna SB No SEB85-17.

Compliance: Prior to issue of Certificate of Airworthiness.

Background: A possibility exists that holes may have been drilled through the muffler allowing exhaust gases into the cabin during cabin heat operation.