

Cessna 177 Series Aeroplanes

AD/CESSNA 177/28

Fuel Cap Alignment Placard

9/80

Applicability: Model 177 with S/Nos. 661, 17700001 to 17702752;

Model 177RG with S/Nos. 177RG0001 to 177RG0177;

Model F177RG with S/Nos. F177RG0001 to F177RG0177.

Requirement: Action in accordance with Cessna SIL No. SE 80-59.

Compliance: Within 100 hours time in service after 30 September 1980.

Background: Correct alignment of flush fitting type fuel caps is essential for efficient operation of the fuel tank secondary vent system.