

Cessna 180, 182 and Wren 460 Series Aeroplanes

---

**AD/CESSNA 180/61**

**Fuel Cap Alignment Placard**

**12/80**

Applicability: Model 180 with S/Nos. 604, 624, 645, 30000 to 32999, 50001 to 50911 and 18050912 to 18053132.

Model 182 with S/Nos. 613, 631, 634, 33000 to 34999, 51001 to 53007 and 18253008 to 18267514.

Model F182 with S/Nos. F18200001 to F18200129.

Model R182/TR182 with S/Nos. R18200001 to R18201460.

Model FR182 with S/Nos. FR18200001 to FR18200045.

Model A182 with S/Nos. A182-0001 and on.

Requirement: Action in accordance with Cessna SIL No. SE 80-59.

Compliance: Within 100 hours time in service after 30 September 1980.

Background: Correct alignment of flush fitting type fuel caps is essential for efficient operation of the fuel tank secondary vent system.