

Cessna 185 Series Aeroplanes

---

**AD/CESSNA 185/30  
Amdt 2**

**Vented Fuel Caps**

**8/86**

Applicability: Models 185 and A185 with S/Nos. 185-00001 to 185-01896.

Requirement: Install vented fuel cap(s) in accordance with Cessna SL No. SE77-6.

*Note: FAA AD 79-10-14, Amendment 39-3475 refers.*

*Note: Installation of a placard is not an acceptable alternative to installation of vented fuel caps.*

Compliance: Within 100 hours time in service after 31 August 1979.

Background: To guard against the possibility of either an obstructed primary vent or sticking of the fuel tank vent valve it has been found necessary to provide secondary venting in the form of vented fuel caps. Due to some misinterpretation of this Directive a Note has now been added to disallow the fitting of a placard. This Directive has been amended to clarify applicable Serial Numbers.