

Cessna 185 Series Aeroplanes

**AD/CESSNA 185/32
Amdt 1**

Alternator Ground Strap

9/82

Applicability: All model 185 with S/Nos. 18501096 to 18503619.

Requirement: Action in accordance with Cessna SIL SE79-59.

Note: FAA AD 79-25-07 refers.

Compliance: 1. Within 100 hours time in service after 31 March 1982.
2. Each time an engine is installed in an aircraft following initial compliance.

Background: Compliance has been amended with the addition of item 2 due to reports from industry that ground straps are being omitted from refitment on engine reinstallations.