

Cessna 185 Series Aeroplanes

AD/CESSNA 185/35

Vertical Fin Rear Spar

12/80

Applicability: Model 185 with S/Nos. 18502311 to 18504070.

Requirement: Action in accordance with Cessna SIL No. SE80-85.

Compliance: Within 100 hours time in service after 31 December 1980.

Background: Overseas, cracks have been found in the flanges and web of the spar below the lower rudder hinge.