

Cessna 206 Series Aeroplanes

AD/CESSNA 206/33

Fuel Cap Alignment Placard

9/80

Applicability: Model 206 with S/Nos. 206-0001 to 206-0275.

Models U206 and TU206 with S/Nos. U206-0276 to U206-1444 and U20601445 to U20605522.

Models P206 and TP206 with S/Nos. P206-0001 to P206-0603 and P20600604 to P20600647.

Requirement: Action in accordance with Cessna SIL No. SE 80-59.

Compliance: Within 100 hours time in service after 30 September 1980.

Background: Correct alignment of flush fitting type fuel caps is essential for efficient operation of the fuel tank secondary vent system.