

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive

Translation of 'Consigne de Navigabilité'
Réf.: 92-045-011(B)

In case of any difficulty, reference should be made to the French original issue.

ATR 72 aircraft

Commercial furnishing

This Airworthiness Directive applies to ATR 72 aircraft, all types all serial numbers.

Incorrect application of the paint scheme may mean that the lining of certain commercial furnishing panels does not compliance with regulation JAR 25-853 a).

A/ ATR 72-101 and -201 aircraft.

In order to comply with the regulations concerning all the commercial furnishing, the following measures are made mandatory :

- As from January 31, 94, all aft RH service doors, aft LH service doors, forward RH service door linings and the frame angles of the flight compartment access door, with manufacturing dates earlier than January 15, 90, are prohibited in service.

B/ ATR 72-102 and -202 aircraft.

In order to comply with the regulations concerning the lining of the aft RH service doors, the following measures are made mandatory :

- As from January 31, 94, all the aft RH service door linings with manufacturing dates earlier than January 15, 90 are prohibited in service.

EFFECTIVE DATE : FEBRUARY 29, 1992

February 19, 92

ATR 72 aircraft

92-045-011(B)