
AIRWORTHINESS DIRECTIVE

For the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PHZL/30.

Propellers - Variable Pitch - Hartzell

AD/PHZL/30 Pitch Change Knob Bushing - Replacement 6/2002

Requirement: CANCELLED

Background: The requirements of this Directive have been adequately addressed. Hartzell SL 69 was issued 9 September 1971 requiring replacement of the pitch change bushing on "Y" shank blades. Blades manufactured after 1971 were to the new F series.



James Coyne
Delegate of the Civil Aviation Safety Authority

1 May 2002