

Propellers - Variable Pitch - Hartzell

---

**AD/PHZL/36**  
**Amdt 2**

**Propeller Blade - Inspection and  
Modification of Balance Cavity**

**8/94**

CANCELLED.

Requirement: Requirements of this directive are now contained in Hartzell's Blade and Repair Manual.