

Propellers - Variable Pitch - Hartzell

AD/PHZL/37

Hard Alloy Blades - Inspection

7/74

Applicability: All blades identified with the letter “H” after the blade design number as follows:

T10173H(-)(-), T10176H(-)(-), T10178H(-)(-) and T10282H (-)(-), excluding the following Serial numbered propellers:

HC-B3TN-2, S/N AG-275 and above.

HC-B3TN-3, S/N BU-4624 and above.

HC-B3TN-5, S/N BV-2210, BV-2213, BV-2214, BV-2216 and above.

HC-B3TN-7, S/N CV-7 and above.

HC-B3TF-7, S/N EX-3 and above.

HC-B4TN-3, S/N EA-255 and above.

HC-B4TN-5, S/N CD-62 and above.

Document: Hartzell SB No. 105A.

Compliance: For blades with less than 1000 hours time in service, within 100 hours time in service after 31 July 1974.

Note: Blades with more than 1000 hours time in service are not affected by this Directive.