

---

## AIRWORTHINESS DIRECTIVE

---

For the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PMC/20.

---

### Propellers - Variable Pitch - McCauley

**AD/PMC/20                      Propeller Hub - Modification or Replacement                      1/2004**  
**(Shot Peening of Blade Retention Threads)**

Requirement:      CANCELLED.

Background:      The requirement to remove certain propeller hubs from service and to shot peen certain propeller hubs as was detailed in this Directive now forms part of the inspection requirements of McCauley Propeller Systems Standard Practices Manual SPM 101-1.



Jim Coyne  
Delegate of the Civil Aviation Safety Authority

4 December 2003