

Restraint Equipment

---

**AD/RES/14**                      **Integral Buckle Assembly, Pacific Scientific**                      **8/83**  
**P/N 1107261-01, -05, -09 Replace Lower Cover**  
**P/N 1107270-01 with Cover Assembly**  
**P/N 1107525-01**

Applicability:    All Pacific Scientific buckle assemblies P/N 1107261-01, 05, -09 manufactured prior to 1982.

Document:        Pacific Scientific SB No. 1107261-25-01, Revision 1.

*Note: FAA AD 83-11-03, Amdt. 39-4662 refers.*

Compliance:     Within six months after 31st August, 1983.

Background:      Entrapment of occupants could result from inability to release the subject restraint system assembly.