

Fokker F28 Series Aeroplanes

AD/F28/60
Amdt 2

Fuselage Lap Joint at Stringer 73

NK

CANCELLED.

Background: The requirements of this Directive have now been incorporated into the F28 Structural Integrity Program. AD/F28/45 Amdt 2 refers.