

Fokker F50 (F27 Mk 50) Series Aeroplanes

AD/F50/1

**Central Windshield Post Connection
to Pressure Bulkhead**

7/88

Applicability: All model F27 Mk 050 aircraft with serial numbers 20104 to 20107 inclusive.

Requirement: Modify in accordance with Fokker Service Bulletin F 50-53-001.

Note: RLD BLA No 88-18 refers.

Compliance: Before exceeding 10,000 flights.

Background: The lug at the bottom of the central windshield post has broken on the manufacturer's fatigue test. A modification has been designed to improve the fatigue resistance of this critical structural joint.