COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

Gulfstream (Grumman) G1159 and G-IV Series Aeroplanes

AD/G1159/31 Amdt 1

Elevator Trim Tab Outboard Hinge Fittings - Inspection

7/82

Applicability: All model GII and GIIB aircraft.

Document: Grumman Customer Bulletin No. 325 Amendment 1. (FAA AD 82-11-02 Amdt. 39-

4384 refers).

Compliance: 1. Unless already accomplished, before further flight after 31 July 1982 - as detailed

in the requirement document.

2. Repeat inspection as detailed in the requirement document until repair or

replacement as detailed in the Aircraft Service Change No. 315.

Background: Manufacturer reports trim tab hinge fitting cracks have occurred. Amendment 1

raised to cover increases in applicability and revisions to repeat inspection, repair or

replacement requirements.