COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, this AD is revoked by CASA ADCX 005/10

British Aerospace BAe 125 Series Aeroplanes

AD/HS 125/6 Aileron Upper Hinge Fairing
Attachment Bolt - Modification

7/2010

Requirement: CANCELLED.

This AD is cancelled on 22 April 2010.

Background: This AD was raised in 1967 against Hawker Siddeley Aviation Service Bulletin (SB)

125-57-18 requiring a modification to prevent fouling of the aileron "A" lever.

Compliance was required within 100 hours time in service.

As this AD has been promulgated for an extended period of time it is considered to be

no longer required. This AD is therefore cancelled.