

British Aerospace BAe 125 Series Aeroplanes

AD/HS 125/49
Amdt 1

Flap Outer Hinge Arm Assembly

9/80

Applicability: All HS/DH/BH 125 series aeroplanes except those with modification 252670 incorporated.

Document: British Aerospace 125 SB No 57-54, Rev 1.

Compliance: Initially inspect before further flight (unless already accomplished) and thereafter inspect at intervals not exceeding 3 months.

Background: The service bulletin revision supersedes the previous alert bulletin, it calls for the removal of the hinge arm for the inspection and applies to additional serial numbered aircraft.