

British Aerospace BAe 125 Series Aeroplanes

AD/HS 125/66 **Main Landing Gear Wheels - Inspection** **8/84**

Applicability: All models HS/DH/BH 125 Series aircraft up to and including Series 700.

Requirement: British Aerospace 125 SB No. 32-201.

Note: The eddy current scan pattern shall be as shown in Fig. 1 of Appendix A and the probe shall be jiggged to ensure that the scan index is accurately maintained.

Compliance: Inspect prior to 31 August 1984, as detailed in the Requirement Document.

Background: Main wheel flange fracture has occurred with resultant structural damage.