

British Aerospace BAe 125 Series Aeroplanes

AD/HS 125/94

Engine Fire Extinguisher Bottle

8/88

- Applicability: All BAe 125 series 700 and 800 and all series retrofitted with Garrett TFE731-3 engines.
- Requirement: Inspect in accordance with BAe Service Bulletin No 26-28.
- Compliance: Prior to 31 May 1989.
- Background: The investigation by the manufacturer into the inadvertent ground firing of a HTL engine fire extinguisher bottle, revealed that the discharge outlet had separated from the fire extinguisher bottle assembly.