
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, this AD is revoked by CASA ADCX 004/10.

British Aerospace BAe 125 Series Aeroplanes

AD/HS 125/119
Amdt 1

MLG Torque Links

6/2010

Requirement: CANCELLED.

This AD is cancelled on 22 April 2010.

Background: This AD was raised in 1991, re-instated and amended in 1998 against British Aerospace Service Bulletin (SB) 32-226-3257A requiring a modification of the MLG torque links. Compliance was not later than 31 May 1992.

This AD was made mandatory by CAA (UK) AD 002-05-91 (applicable to 800A and B series) and FAA AD 92-15-04 (applicable to 800 series only).

As this AD required a one-time modification and has been published for an extended period, it is considered to be no longer required. This AD is therefore cancelled.