

British Aerospace BAe 125 Series Aeroplanes

AD/HS 125/135

**Fire Protection Circuitry - Inspection
of Blocking Diodes**

4/93

Applicability: All series 125 aircraft identified in Corporate Jets Limited Service Bulletin S.B. 26-33 dated 8 December 1992.

Requirement: Action in accordance with the Accomplishment Instructions of Corporate Jets Limited Service Bulletin S.B. 26-33 dated 8 December 1992.

Note: This Service Bulletin has been classified as Mandatory by the CAA(UK), AD 012-12-92 refers.

Compliance: Prior to 1 May 1993.

Background: This Directive has been issued following reports of isolated cases of dormant failure of the blocking diodes associated with the 'EXT FIRED' (bottle gone) indicators. Compliance with this Directive will provide improved system integrity.