

British Aerospace BAe 125 Series Aeroplanes

AD/HS 125/144

Elevator Pulley Assembly

11/94

- Applicability: Model BAe Series 1000A and B, and Hawker 1000 aircraft as identified in the Requirement Document.
- Requirement: Action in accordance with Hawker Raytheon Corporate Jets Mandatory Service Bulletin 27-161.
- Compliance: Prior to 31 March 1995.
- Background: The manufacturer had received reports of incorrectly assembled elevator pulley installations on some in-service aircraft.