

British Aerospace BAe 125 Series Aeroplanes

AD/HS 125/152

Hydraulic Pipes

7/95

Applicability: All BAe 125 series 1000A, 1000B and Hawker 1000 aircraft.

Requirement: Action in accordance with Hawker Raytheon Corporate Jets Mandatory Service Bulletin SB.29-95.

Note: This SB has been classified as Mandatory by the UK CAA.

Compliance: By 31 June 1995.

Background: The manufacturer has advised that chafing between the equipment bay structure and hydraulic lines has been reported.