

Israel Aircraft Industries 1123 and 1124 (Westwind) Series Aeroplanes

AD/IAI-W/11 Elevator and Rudder Servo Installation 5/86

Applicability: Model 1124 and 1124A Westwinds, all serial numbers prior to 437 except 418, 423, 426, 429, 431, 432 and 435.

Requirement: Action in accordance with 1124 Westwind Service Bulletin No 1124-22-072.

Compliance: Within 100 hours time in service after 31 May 1986.

Background: The manufacturer has identified the possibility of elevator and/or rudder control interference with existing hardware.