

British Aerospace (Scottish Aviation) Twin Pioneer Series Aeroplanes

AD/SA-TP/26
Amdt 1

Flap Operating System

1/87

Applicability: All models.

Requirement: Action in accordance with Scottish Aviation TNS 50 issue 3.

Compliance: Within 200 hours time in service after last compliance with the previous issue of this Directive prior to 31 January 1987 and thereafter every 200 hours time in service.

Background: This amendment reflects the later issue of the TNS which extends compliance to 200 hours time in service.