COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

SAAB SF340 Series Aeroplanes

AD/SF340/7 Power Turbine Speed 8/87
Amdt 1 Signal - Overspeed Protection

Applicability: SAAB 340A Aircraft.

Requirement: Action in accordance with SAAB Service Bulletin SF 340-76-018.

Note: Swedish Airworthiness Directive SAD NO. 1-021 refers.

Effectivity: 31 July 1987.

Background: This amendment has been raised to incorporate the final closing action for overspeed

protection to prevent engine power turbine overspeed and with it the risk of

uncontained engine failure. The amendment supersedes the FAA Telegraphic AD

T86-10-51.