

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/SF340/54 Amdt 2.

---

### SAAB SF340 Series Aeroplanes

**AD/SF340/54  
Amdt 2**

**Ceiling and Lavatory Lights**

**1/2010**

Requirement: CANCELLED.

This AD is cancelled on 11 January 2010.

Background: A routine review of Airworthiness Directives for SAAB 340 model aeroplanes revealed that AD/SF340/54 Amdt 1 erroneously removed the requirements of Swedish Luftfartsverket (LFV) SAD 1-103 whilst incorporating the requirements of LFV SAD 1-113. To ensure that the requirements of both LFV SAD 1-103R1 and 1-113R1 are complied with, and at the same time to avoid confusion, this Directive is cancelled and two new Directives have been published as AD/SF340/109 and AD/SF340/110.



Mike Higgins  
Delegate of the Civil Aviation Safety Authority

5 January 2010